

Division of Oil, Gas, & Mining
Mining Report

07/27/92

MINE ID: M045017

MINE NAME: MERCUR MINE

OPERATOR: BARRICK MERCUR GOLD MINES, INC
CONTACT: GLENN M EURICK
ADDRESS: P O BOX 838
TOOELE UT 84074

PHONE: (801)268-4447

Surface Owner: PRIVATE BLM #:
Mineral Owner: PRIVATE Lease #:

Qtr-Qtr-Qtr1	Qtr-Qtr1	Qtr1	Qtr-Qtr-Qtr2	Qtr-Qtr2	Qtr2	Sec	Range	Town
		PR				4	3.0W	6.0S
						8	3.0W	6.0S
						32	3.0W	5.0S

Permit Status: APP Mine Type [(S)urface, (U)nderground]: S

Mine Status (PRO,ACT,SUS,RET): ACT Acreage: 892

Minerals Mined
AU, AG

DATE RECEIVED	TENTATIVE APPROVAL DATE	FINAL APPROVAL DATE	LAST INSPECTED
---------------	-------------------------	---------------------	----------------

03/10/81	05/01/81	10/13/81	07/14/92
----------	----------	----------	----------

BOND TYPE: SELF BOND

BOND AMOUNT: 8,808,891

ANNUAL REPORT YEAR: 91

NONCOMPLIANCE NOTICES: 0	DATE ISSUED: / /	DATE RESOLVED: / /
VIOLATIONS: 0	DATE ISSUED: / /	DATE RESOLVED: / /
REVISIONS: 0	DATE REC'D: / /	DATE APPROVED: / /
AMENDMENTS: 0	DATE REC'D: / /	DATE APPROVED: / /

COMMENTS:

Inspection made to discuss ongoing dump leach #3 construction. Also to evaluate cyanide solution spill of 40-60 lbs sodium cyanide. Structures not adequate to handle such a spill of this magnitude. JBR working w/operator to see if a clay cap needs to be installed over dump leach #3.

INSPECTION 7/92 TO EVALUTE THE PROPOSED SUNRISE DUMP RECONFIGURATION. PROPOSAL WILL ALLOW MORE GRADUAL SLOPES & LESS ROAD DISTURBANCE. THIS PROPOSAL IS MUCH BETTER THAN THE ORIGINAL. OPERATOR TO ADDRESS QUESTIONS RAISED DURING INSPECT.